

It's Raining in Our Music Room

Recently we were approached by one of our clients regarding an ongoing humidity problem. The problem was portrayed to us as “it is raining in the music room can you help us?” Too much humidity can have detrimental effects in many ways on musical instruments. The building posed certain challenges due to the type of usage. When a building or an area of a building is only occupied for a very short period of time throughout any given day special consideration is needed to properly size the air conditioning equipment to account for the sporadic load.



Our project team provided a “Linc Service Building Analysis” to assess the problem at hand. Next we partnered with a trusted manufacturer’s representative to develop a solution for their problem.

VASEY thrives on challenges of this nature. This is why we consider ourselves a “complex solution provider.”

After thorough research we integrated state of the art equipment with an existing building automation system to control the environment within acceptable parameters. The equipment is capable of multiple stages of cooling and humidity control logic that allows the client precise control of their indoor comfort.

If you have an issue that you cannot seem to solve, you can trust that VASEY is equipped with the tools and the knowledge to address any of your complex needs.

At risk? Not sure? Call VASEY at 317-873-2512. We can help protect your organization from downtime and loss due to temperature and humidity challenges. If nothing else, call us for peace of mind!

Contact Information:

Roger Mooney

Sales Manager

rmooney@vaseycommercial.com

MOBILE: 317-710-4877

VASEY Commercial Heating & Air Conditioning
10830 Andrade Drive
Zionsville, IN 46077

WEBSITE: www.VASEY.biz

TEL 317-873-2512

FAX 317-873-1566